# Install Stenograph® Writers USB Drivers

The Stenograph Install Drivers program runs a wizard to easily install your Stenograph writing machine USB drivers.  The USB drivers are for Stenograph writers (Luminex™, Diamante®, Wave®, élan Mira®, élan Cybra®, Stentura Fusion® and Stentura Protégé®) for use with Case CATalyst® and other compatible CAT software.

1. Navigate to the location where you extracted the USB Writer Drivers folder.

2. Double click the **USB Writer Drivers** folder.  Inside the folder, you will find a Drivers folder, StenographDriverInstall.exe, RemoveDrivers.exe and PDF.

3. Double click the **StenographDriverInstall**.exe.  The Stenograph Writer Drivers Setup dialog box displays:



4. Once the drivers install the Stenograph Writer Drivers Setup Complete dialog box displays.  Press **Enter** (Finish) to close the wizard.



5. Turn your Stenograph writer On.

6. Plug the USB cable into your computer's USB port and the other end of the USB cable into the writer's USB port.  You may see a small Windows operating system bubble display information about installing the driver.  Once the driver is installed, follow your CAT system's instructions for connecting to the writer.